

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1543
North
> 1
1.945 mi.
10272 ft.

INTERSECTION
NW CORNER OF AVE P AND W 4TH ST
BROOKLYN, NY

NY Spills **S111239047**
N/A

Relative:
Higher

Actual:
28 ft.

SPILLS:

Name: INTERSECTION
Address: NW CORNER OF AVE P AND W 4TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1107849 / 2011-10-20
Facility ID: 1107849
Facility Type: ER
DER Facility ID: 410138
Site ID: 455560
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2011-09-21

Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2011-09-21
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-09-21
Spill Record Last Update: 2011-10-20
Spiller Name: ANATOLIY NASIMOV
Spiller Company: AMG TRANSPORTAION, INC
Spiller Address: Not reported
Spiller Company: 999
Contact Name: VANILYAM ARMEN
DEC Memo: "09/21/11-Hiralkumar Patel. 11:44 AM: spoke with Anatoliy Nasimov at AMG Transportation, which is a private medical transportation service. he mentioned that driver responded to call from 273 Ave P. lateron, driver noticed gasoline leaking from tank and suspected that someone tried to steal gasoline from their van. oil spilled onto street only. no soil/sewer was impacted. FDNY cleaned up the spill. asked Anatoliy to call back with information about who removed the contaminated material (probably in drum) from the site. Anatoliy will talk to driver and will call back. 12:40 PM:- left message for Fire Chief (718-965-8208). 12:50 PM:- received call from Anatoliy. he asked to call his mechanic, Fikret (917-295-3840). 12:54 PM:- spoke with Fikret. he mentioned that he received only the van and did not received any drum of contaminated material. 09/22/11-Hiralkumar Patel. 9:30 AM:- visited intersection. found a 20 gal drum (probably filled with product and contaminated material) and plastic bag full of contaminated speedy dry. also found oil in catch basin in northwest corner of the intersection. found two manhole cover plates in area of spill: one marked as DWS and another marked as FDNY. 9:38 AM:- left message for Anatoliy. 9:40 AM:- received call from Anatoliy. informed him that contaminated material (and probably

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

product also) still on-site and oil in catch basin. informed him that site must be cleaned by the end of today. he requested a site meeting. 11:10 AM:- revisited site. met Anatoliy. explained him current situation and informed him that AMG Transportation is responsible for complete cleanup as oil spilled from AMG's vehicle. at beginning, Anatoliy refused to take responsibility and mentioned that someone tried to steal oil from his vehicle and that is not his fault. after further discussion, he agreed to cleanup the spill. informed him that oil from catch basin must be cleaned up by end of today. Anatoliy Nasimov President AMG Transportation, Inc. Ph. (516) 792-1674/1675 (O) (718) 781-3092 (C) Fax (516) 792-1676 email: amg_transportation@yahoo.com anasim.amg@gmail.com Jack Schloss **AMG's attorney** Schloss & Schloss Ph. (845) 425-4200 Fax (845) 425-4404 11:47 PM:- received call from Anatoliy. he has hired ABC tank for required cleanup. 1:03 PM:- received call from Chris from ABC. he has sent cleanup crew to the site. asked him to call back once cleanup completed. 09/23/11-Hiralkumar Patel. received message from Chris (at 6:32 PM on 09/22/11) stating that cleanup was completed. 10:08 AM:- spoke with Chris. he confirmed that cleanup was completed and will submit disposal manifest. 10/12/11-Hiralkumar Patel. received disposal manifests (on 09/29/11) from ABC Tank. 10/20/11-Hiralkumar Patel. based on available information, case closed."

Remarks:

"clean up -in progress - speedy dry"

All Materials:

Site ID: 455560
Operable Unit ID: 1205711
Operable Unit: 01
Material ID: 2202645
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 15.00
Units: G
Recovered: Not reported
Oxygenate: Not reported